

FIG.1




FIG.4

2/3

$C_1$	00000001	$C_1^{bc}$
$C_1$	00000010	$C_1^{RACH}$
$C_1$	00000011	$C_1^1$
$C_1$	00000100	$C_1^2$
$C_2$	00010000	$C_2^{bc}$
$C_2$	00000001	$C_2^{RACH}$
$C_2$	00000010	$C_2^1$
$C_2$	00000100	$C_2^2$
$C_5$	00100000	$C_5^{bc}$
$C_5$	00100001	$C_5^{RACH}$
$C_5$	00100010	$C_5^1$
$C_5$	00100011	$C_5^2$

FIG.2




FIG.3